



Report Number: MIC-ASI213862

**Audit Date** : 30 Jun., 2021

This report is issued by Focus Technology Co., Ltd. (Made-in-China.com) and the supervising inspectorate (Bureau Veritas) to confirm that:

Company Name : ZHEJIANG LIONKING VENTILATOR CO., LTD.

浙江莱恩克风机有限公司

Showroom: https://lkventilator.en.made-in-china.com

Address : No. 688, Yangsi Road, Zhangan, Jiaojiang District, Taizhou City,

**Zhejiang Province, China** 

Product : Air Conditioning Fan, Engineering Fan, Siren, Forward Curved

Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial

Fan, Roof Fan, Box-Type Fan


#### has been on site audited for the Following Scope of Activity

1. General Information

- 2. Foreign Trade Capacity
- 3. Product Research & Development Capacity
- 4. Management System and Product Certification
- 5. Production Capacity & Quality Control
- 6. Working Environment
- 7. Energy Saving and Emission Reduction
- 8. Photos

# General Comments:

ZHEJIANG LIONKING VENTILATOR CO., LTD. is a manufacturer with 94 employees; it was established in 2015, located in No. 688, Yangsi Road, Zhangan, Jiaojiang District, Taizhou City, Zhejiang Province, China. The company occupies an area of about 25000 square meters. ZHEJIANG LIONKING VENTILATOR CO., LTD. has successful foreign trading experience in North America, South America, Europe, Southeast Asia/ Mideast, Africa, Domestic.



Sign for and on behalf of Bureau Veritas



This document is used by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is at information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and resolvent in the limits of Client's instructions, if any. The company's sole responsibility is to the safety and readily accessible portions of consignment and resolvent in the limits of Client's instructions, if any. The company's sole responsibility is to the safety and readily accessible portions of the content. Any content is unlawful and obligations under the transaction document. Any contents in the safety and readily accessible portions of consignment and readily accessible portions of consignme

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 1 of 19





# SUPPLIER ASSESSMENT REPORT

Audited Company	ZHEJIANG LIONKING VENTILATOR CO., LT	D.	
	浙江莱恩克风机有限公司		
Audited Site:	No. 688, Yangsi Road, Zhangan, Jiaojiang District, Taizhou City, Zhejiang Province, China		
Consigner of Assessment	Made-in-China.com		
Audit Type	<ul><li>☑ Initial Audit</li><li>☐ Re-audit</li></ul>	MILLS ASSECTED	60 A
Audit Date	30 Jun., 2021	Verify Report	http://www.bvcerchina.cn
Auditor	Wenjing Shi	Reviewed by	Rosy Cheng

#### CONTENTS

## Part A: General Information

Section 1: Company Overview

Section 2: Human Resources

### □ Part B: Foreign Trade Capacity

Section 1: Export Overall Situation

Section 2: Export Business Capacity

Section 3: Supplier Management

Section 4: After-sales Service Capacity

### □ Part C: Product Research & Development Capacity

Section 1: Product Research & Development Capacity

#### Part D: Management System and Product Certification

Section 1: Management System(s) and Product Certification

#### □ Part E: Production Capacity & Quality Control

Section 1: Production Capacity Section

Section 2: Production Process Control

### Part F: Financial Position

Section 1: Financial Data

Section 2: Key Performance Indications

Section 3: Banking

Section 4: Product Insurance

#### Part G: Working Environment

Section 1: Working Environment

### Part H: Energy Saving and Emission Reduction

Section 1: Environmental Management

Section 2: Water, Gas and Noise Control

#### Part I: Industry Information

Section 1: Industry Information

#### □ Part J: Photos

Section 1: Photos of Documents

Section 2: Photos of Company

ureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment adings at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to especially a transaction from exercising all their tights and obligations under the transaction document. Any or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 2 of 19







### **Part A: General Information**

# **Section 1: Company Overview**

1.1 Legal Validity			
Does the company have a valid business license?	☐ Yes ☐ No ☐ Others	Registration Number	9133100235539423XB
Year of established	02 Sep., 2015	Valid Date	01 Sep., 2045
Registered address	No. 688, Yangsi Road, Zhangan, J China	liaojiang District, Tai	zhou City, Zhejiang Province,
Actual address	No. 688, Yangsi Road, Zhangan, J China	liaojiang District, Tai	zhou City, Zhejiang Province,
Does the company in abnormal operation status list of industrial and commercial bureau?	No		
Registered capital	RMB 51800000		
Name of legal representative	Mr. Liangren Wang		
Business scope	Fan, motor, alarm, alarm control equipment, rescue equipment, social and public safety equipment and equipment, plastic products manufacturing and sales; Import and export of goods and technology.		
1.2 Basic Information			
Contact person	Mr. David Zheng		
Phone number	0086-15888602172	Fax number N	I/A
URL/Web address	https://lkventilator.en.made-in-china	a.com	
Company type		Company Corporation	
Type of ownership	<ul><li>☐ Limited Company</li><li>☐ Public C</li><li>☐ State-Owned</li><li>☐ Private</li></ul>	• •	gn joint venture ly foreign-owned enterprises
Associated company	No associated company		-
Products manufactured / sold scope	Air Conditioning Fan, Engineering I Backward Curved Centrifugal Fan,		
1.3 Company Building Informat	ion		
According to:  Land certificate  Chease agreement  Real estate certificate  Chease agreement  Observation Estimated on site  The company area 25000 square meters  The land occupies 25000 square meters.  The offices occupy 5000 square meters.			
The workshops occupy 20000 square	The workshops occupy 20000 square meters.		

This document of the safety and readily accessible portions of consignment and the safety accessible portions of consignment and the safety accessible portions of the safety accessible portions


ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 3 of 19





### **Section 2: Human Resources**



Remark: Above information of key staff was based on interview with company representative.

This document of the Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and processes the protocological protocolog

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 4 of 19





# Part B: Foreign Trade Capacity

### **Section 1: Export Overall Situation**

1.1 Export Overall Situation	
Does the company have a valid Import and Export license?	⊠ Yes □ No
The import and export enterprise code.	9133100235539423XB
The number of foreign trading staff with relevant trading experience.	☐ within 1 year staff ☐ 1-5 years 2 staffs ☐ 6-10 years 2 staffs ☐ over 10 years 2 staffs ☐ Total 6 staffs
The language freely used by foreign trade staff	□ English □ others:
Annual revenue of previous year	Confidential
Annual export revenue of previous year	Confidential
Estimated export revenue for this year.	Confidential
Overseas agent / branch	☐ Yes
Nearest port	Ningbo Port, Shanghai Port
Acceptable quotation terms	☑ FOB ☑ CIF ☑ CFR
Acceptable payment terms	<ul><li>□ LC</li><li>□ T/T</li><li>□ D/P</li><li>□ PayPal</li><li>□ Small-amount payment</li></ul>
Average lead time (Peak Season)	<ul><li> within 15 workday</li><li> □ one month</li><li> □ 2-3 months</li><li> □ 4-6 months</li><li> □ 6-12 months</li><li> □ more time</li></ul>
Average lead time (Off Season)	<ul><li> within 15 workday</li><li> □ one month</li><li> □ 2-3 months</li><li> □ 4-6 months</li><li> □ 6-12 months</li><li> □ more time</li></ul>

# **Section 2: Export Business Capacity**

2.1 Market Distribution (plea	2.1 Market Distribution (please list top three areas)		
Market	Main Product	Main client	
North America     ■     North America     North Ame	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	
South America     Sou	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	
□ Europe	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	
Southeast Asia/ Mideast	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	
	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	
□ Domestic     □	Air Conditioning Fan, Engineering Fan, Siren, Forward Curved Centrifugal Fan, Backward Curved Centrifugal Fan, Plug Fan, Axial Fan, Roof Fan, Box-Type Fan	Confidential	

is document of the Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of some of the safety and readily accessible portions of consignment described in the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of consignment and incompanies of the safety and readily accessible portions of the consignment and incompanies of the safety and readily accessible portions of the safety accessible portions of the s

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 5 of 19





# **Section 3: Supplier Management**

3.1 Supplier Management			
Item	Content	Observations /Comments	
1	Does the company establish and implement an effective suppliers' assessment procedure?	<ul> <li>☐ Have the written procedures and followed records</li> <li>☐ Have the written procedures but no records</li> <li>☐ Have relevant records without written procedure</li> <li>☐ No written procedures or followed records</li> <li>☐ Other</li> </ul>	
2	Does the company have an updated list of approved suppliers?	<ul> <li>☑ The approved suppliers list was updated in</li></ul>	

# **Section 4: After-sales Service Capacity**

4.1 After-sa	4.1 After-sales Service Capacity		
Item	Content	Observations /Comments	
1	Is there a procedure to conduct random product inspection after final packaging in place?	<ul> <li>☐ Have clear standards and written inspection records</li> <li>☐ No written standards but had inspection reports</li> <li>☐ Have the procedures but no inspection records</li> <li>☐ It's not necessary to carry out the inspection</li> <li>☐ Other</li> </ul>	
2	Is there a clear procedure for handling customer complaints?	<ul> <li>☐ Has the clear procedure and followed records</li> <li>☐ Has the procedure but no written records.</li> <li>☐ No written procedures or records.</li> <li>☐ Other</li> </ul>	
3	Can the finished/packaged product be traced by lot identification to the appropriate raw materials test reports?	<ul> <li>☐ Have the procedures to trace the raw materials.</li> <li>☐ Can trace main materials</li> <li>☐ Can trace production date.</li> <li>☐ Can't trace products</li> <li>☐ Other</li> </ul>	
4	Are corrective & preventive actions mechanism established and implemented effectively (including the suppliers/ sub-contractors control, incoming inspection, process control, final inspection and customer complaint)?	<ul> <li>☐ Has the clear procedure and followed records</li> <li>☐ Has the procedure but no written records.</li> <li>☐ No written procedures or records.</li> <li>☐ Other</li> </ul>	

This docume and by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and jurisdiction issues defined therein. Any holder of this document and jurisdiction issues defined therein. Any holder of this document is unlawful and readily accessible portions of consignment and jurisdiction and information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and jurisdiction issues defined therein. Any unlawful and obligations under the transaction document. Any unlawful and offenders may be prosecuted to the fullest extent

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 6 of 19







# Part C: Product Research & Development Capacity

1.1 Product Research & Development Capacity	
The amount of R&D and relevant working experience.	☐ within 1year staff ☐ 1-5 years staff ☐ 6-10 years staff ☐ over 10 years 2 staffs  Total 2 engineers
What is the main job responsibility for R&D engineers?	Technology engineers were responsible for confirming customer's request, providing technical support for production and after-sales service.
Is there any relevant design input, output, review, verification and validation documentation available for auditor to review?	Yes
Is there any special software or instrument used by the R&D staffs during the design process of new products?  If yes, please list the main software or instrument.	Yes, CAD, Solidworks, UG
Does the company have an effective design change control procedure in place?	Yes
Please list the patent certificates and qualification license.	Nil

This docume the displacement of the same displ

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 7 of 19



# **Part D: Management System and Product Certification**

1.1 Management System and Product Certification	
Management system certification	□ ISO9001:2015 certificate Certificate Name: ISO9001:2015 certificate NO.: 626019Q13540R1S Issued by: Kaixin Certification (Beijing) Co., Ltd. Issued Date: 04 Jan., 2019 Valid Until: 03 Jan., 2022 Scope: N/A  □ ISO14001:2015 certificate Certificate Name: ISO14001:2015 certificate NO.: 60021E0141R0S Issued by: Zhongrui Certification (Zhejiang) Co., Ltd. Issued Date: 06 May, 2021 Valid Until: 05 May, 2024 Scope: N/A  □ Others Certificate Name: ISO45001:2018 certificate NO.: 06919S11167R1S Issued by: Kaixin Certification (Beijing) Co., Ltd. Issued Date: 07 Feb., 2021 Valid Until: 03 Jan., 2022 Scope: N/A
Product certification	□ CE
	□ UL □ CCC □ RoHS □ FCC □ Others Certificate Name: Fire Product Certification NO.: z2017081814002585 Product Name: Smoke Exhauster Model: N/A Standard: N/A Scope: N/A Issued by: CNAS Issue Date: 02 Aug., 2019 Certificate Name: Fire Product Certification NO.: Z2017081814002586 Product Name: Smoke Exhauster Model: N/A Standard: N/A Scope: N/A Issued by: CNAS Issue Date: 02 Aug., 2019 □ NIL
Test reports for raw materials	☐ RoHS
	Reach
	Others
	⊠ NIL

This document of the safety and readily accessible portions of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of the safety and readily accessible portions of consignment and price of the safety and readily accessible portions of the safety accessible portions of the safety

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/


Page No.: 8 of 19





# **Part E: Production Capacity & Quality Control**

### **Section 1: Production Capacity**



This docume and by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document at information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and the limits of Client's instructions, if any. The company's sole responsibility is to its desired the solution of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent unlawful and offenders may be prosecuted to the fullest extent.

nticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 9 of 19







	CNC Lathe	China	Confidential	22
1723	Cutting Facility	China	Confidential	6
	High Speed Punch	China	Confidential	16
	Hydraulic Press	China	Confidential	4
	Laser Cutting Facility	China	Confidential	2

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 10 of 19





### **Section 2: Production Process Control**

2.1 Pro	2.1 Production Process Control		
Item	Content	Observations /Comments	
1	Product R&D capacity	<ul><li>☑ Own brand</li><li>☑ ODM</li><li>☑ OEM</li></ul>	
2	Are the environmental conditions, such as tidiness and cleanliness being controlled and suitable for the operation performed?	<ul><li>□ Very tidy</li><li>☑ Normal</li><li>□ Need to improve</li><li>□ Very poor</li></ul>	
3	Are the necessary items /documents provided at appropriate location and under control?	<ul> <li>☑ Work Instructions /procedures</li> <li>☐ Workmanship standard /acceptance</li> <li>☐ Golden sample /Approval sample</li> <li>☐ Product picture</li> <li>☐ Verbal by workshop director</li> </ul>	
4	Are written instructions available for incoming material inspections /testing? Is the relevant record maintained?	<ul><li>☐ Has instructions and uniformly followed</li><li>☐ Has instruction but no written records</li><li>☐ Materials checked by storage staff</li></ul>	
5	Are written inspections /testing instructions available for finished products? Is the relevant record maintained?	<ul><li>☐ Have instructions and uniformly followed</li><li>☐ Have instruction but no written records</li><li>☐ Finished product checked by packing staff</li></ul>	
6	What type of inspection is used for finished products?	<ul> <li>□ Random inspection</li> <li>□ Visual inspection</li> <li>□ Function inspection</li> <li>☑ 100% inspection</li> <li>☑ Visual inspection</li> <li>☑ Function inspection</li> </ul>	
7	Are non-conforming units clearly marked/ segregated to prevent accidental dispatch?	<ul><li>✓ Marked and segregated</li><li>✓ Segregated but not marked clearly</li><li>✓ Not found on site</li></ul>	
8	How are the non-conforming units handled?	<ul> <li>☐ Repaired and re-inspection</li> <li>☐ Picked out</li> <li>☐ Used under control</li> <li>☐ Others</li> </ul>	

This docume as a set of by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and provide an information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and provide an information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of consignment and provide an information of the safety and readily accessible portions of the safety and provide an information of the safety a

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 11 of 19





# **Part G: Working Environment**

# **Section 1: Working Environment**

1.1 Welfa	re Benefits	
Item	Content	Observations /Comments
1	Does the company have effective procedures to verify the age of staff at the time of recruitment?	<ul> <li>☐ Has written procedure and keeps adequate age documents of workers</li> <li>☐ Has written procedure but doesn't follow records</li> <li>☐ Hasn't written procedure or follows records</li> </ul>
2	Do all workers sign employment contracts with the factory?	<ul> <li>✓ All workers sign employment contracts</li> <li>☐ Some workers sign employment contracts</li> <li>☐ Only management staff sign employment contracts</li> <li>☐ No staff sign employment contracts</li> </ul>
3	Is statutory contribution required for all employees' social insurance (e.g. health insurance, unemployment insurance, accident insurance etc.) paid for by the enterprise?	<ul> <li>☐ All workers have social insurance.</li> <li>☑ Some workers have social insurance</li> <li>☐ Only management staffs have social insurance</li> <li>☐ No staff have social insurance</li> </ul>
4	Does the company have a clear and effective policy on working hours, rest and vacations? If does, please list it.	<ul> <li>All staffs work kept to the policy</li> <li>Most of the time it keeps to the policy except midseason.</li> <li>Usually needs overtime.</li> <li>No relevant records for working hours</li> <li>Describe the working hours: From Monday to Saturday; 08:00-11:30, 12:30-17:00</li> </ul>
5	Does the company pay extra remunerations for all overtime work?	<ul> <li>☐ For all overtime work.</li> <li>☐ For official holidays</li> <li>☐ For official holidays except weekend.</li> <li>☐ No extra remunerations for overtime.</li> </ul>
6	Does the company have dormitories for staff? If yes, please describe the condition.	<ul> <li>☑ Provide dormitories for all staff</li> <li>☐ Provide dormitories for workers</li> <li>☐ Provide dormitories for management staff</li> <li>☐ No dormitories were provided.</li> <li>Describe the condition: One Person/One Room, Two People/One Room</li> </ul>
1.2 Labor	Protection	
Item	Content	Observations /Comments
1	Are there uniforms for all staff in company?	<ul><li>Yes</li><li>No</li><li>Other</li></ul>
2	Is the emergency medical supplies enough and easily used in workshop?	<ul><li>Yes</li><li>No</li><li>Other</li></ul>
3	Does the company arrange health and safety training for new workers?	<ul><li>☐ Yes</li><li>☐ No</li><li>☐ Other</li></ul>
4	Do the workers have the appropriate protective equipment during operation in workshop? Such as gloves, masks.	<ul><li>☐ Yes</li><li>☐ No</li><li>☐ Other</li></ul>
5	Is there training needed and carried out for fire protection?	<ul><li>✓ Yes</li><li>☐ No</li><li>☐ Other</li></ul>

d by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of its document of the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment in the limits of Client's instructions, if any. The company's sole responsibility is the safety and readily accessible portions of consignment in the limits of Client's instructions, if any. The company's sole responsibility is the safety and obligations under the transaction document. Any provided in the safety and safety and obligations under the transaction document. Any provided in the safety and s

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 12 of 19



# **Part H: Energy Saving and Emission Reduction**

# **Section 1: Environmental Management**

1.1 Environmental Management			
ltem	Content	Observations /Comments	
1	Environmental Management System	<ul><li>☑ ISO 14001 Certificate</li><li>☐ Cleaner production management</li><li>☐ NIL</li></ul>	
2	Environmental Impact Assessment	<ul><li>☐ The Report of Environmental impact assessment is approved by EPA .</li><li>☒ NIL</li></ul>	
3	Check and Acceptance of Completed Constructive Projects	<ul> <li>☐ The Report Completed Constructive Projects Inspection and Acceptance is approved.</li> <li>☑ NIL</li> </ul>	
4	"Three Simultaneity" for Environmental protection	<ul> <li>☐ The Report of "Three Simultaneity" for Environmental protection Inspection and Acceptance is available.</li> <li>☒ NIL</li> </ul>	

### Section 2: Water, Gas and Noise Control

2.1 Water, Gas and Noise Control		
Item	Content	Observations /Comments
1	Water-intaking	<ul><li>☐ Water-intaking license</li><li>☐ No water-intaking license</li><li>☒ No water taken from natural water body</li></ul>
2	Waste water	<ul> <li>□ Water-draining license or contract</li> <li>□ Having carried out waste water treatment before draining</li> <li>□ Having carried out waste water monitoring and the result of which being within the standard limit</li> <li>☑ No detail activities were found</li> </ul>
3	Emission to air	<ul> <li>☐ Air pollutant emission license</li> <li>☐ Having carried out air pollutant emission monitoring and the result of which being within the standard limit</li> <li>☒ No detail activities were found to reduce emission to air</li> </ul>
4	Classification and Recycling for solid waste	<ul> <li>☐ Having applied trash classification recycling</li> <li>☐ Having special warehouse for hazardous waste</li> <li>☐ No detail activities were found</li> </ul>
5	Noise	<ul> <li>☐ The company carried out noise monitoring and the result of which being within the standard limit one time per year</li> <li>☒ No detail activities were found</li> </ul>

This docume and by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and jurisdiction issues defined therein. Any holder of this document and jurisdiction issues defined therein. Any holder of this document is unlawful and readily accessible portions of consignment and jurisdiction and information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and jurisdiction issues defined therein. Any unlawful and obligations under the transaction document. Any unlawful and offenders may be prosecuted to the fullest extent

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 13 of 19





## Part J: Photos

### **Section 1: Photos of Documents**

1.1 Photos of Documents





### **Description: ISO90012015 Certificate**



**Description: ISO140012015 Certificate** 

**Description: Export License** 



### **Description: ISO450012018 Certificate**



**Description: Fire Product Certification** 



ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 14 of 19









This document of the Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and provided the same of the safety and readily accessible portions of consignment and provided the same of the safety and readily accessible portions of consignment and provided the same of the safety and readily accessible portions of consignment and provided the same of the safety and readily accessible portions of consignment and provided the same of the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of the safety accessible portions of the safety and readily accessible portions of the safety accessible portions

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 15 of 19





# **Section 2: Photos of Company**

# 2.1 Photos of Company and Product Sample

**Description: Company Gate** 



**Description: Office** 



**Description: Office** 



**Description: Office** 



**Description: Office** 



**Description: Office** 



d by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of its document of the safety and readily accessible portions of consignment and provided the safety and readily accessible portions of consignment in the limits of Client's instructions, if any. The company's sole responsibility is the company's sole responsibility is the content of a transaction from exercising all their tights and obligations under the transaction document. Any provided the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extensive the content of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extensive the content of the content of the content of the content of this document is unlawful and offenders may be prosecuted to the fullest extensive the content of the co

nticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 16 of 19







**Description: Test Facility** 



**Description: Test Facility** 



**Description: Workshop** 



**Description: Workshop** 



**Description: Workshop** 



**Description: Workshop** 



is document of by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of its document of the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and readily accessible portions of consignment and provided in the safety and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible portions of consignment and provided in the safety accessible provi

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 17 of 19







### **Description: Workshop**





**Description: Workshop** 

**Description: Workshop** 



**Description: Product Sample** 



**Description: Product Sample** 





This docume and by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety and readily accessible portions of consignment and in the safety accessible portions of consignment and in the safet

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 18 of 19







### **Description: Product Sample**





-- End of the Report --

This document of by Bureau Veritas. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document information contained hereon is solely limited to visual examination of the safety and readily accessible portions of consignment and providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any. The company's sole responsibility is to its providing at the time of its intervention only and within the limits of Client's instructions, if any client's instruction is a sole of the company of the company

ticity of testing/inspection report & certificate, please click: http://www.bvcerchina.cn/

Page No.: 19 of 19